

Colibri Scan Report

Left Fender 4 H	Hood 49 H 6 OS	Right Fender 2 H 1 OS		
Left Front Door 2 H 1 OS	Left Rail 11 H 3 OS	Roof 120 H 26 OS 1 DOS	Right Rail 3 H	Right Front Door 11 H 1 OS
Left Rear Door 4 H				Right Rear Door 4 H 1 OS
Left Quarter 7 H	Trunk No Dents	Right Quarter No Dents		

Licence Plate
188998 (2018)

VIN

Car Brand
TOYOTA


Car Model
TUNDRA

Total Dents
All: 217

HalfDollar: 177

Oversize: 39

D-Oversize: 1



Colibri Scan Report

Default Table

Matrix Summary

Panel	Type	Group	Oversize	D-Oversize	Total
Hood	HalfDollar	31-50	6		49
Right Fender	HalfDollar	1-5	1		2
Left Fender	HalfDollar	1-5			4
Roof	HalfDollar	101-150	26	1	120
Right Rail	HalfDollar	1-5			3
Left Rail	HalfDollar	6-15	3		11
Right Front Door	HalfDollar	6-15	1		11
Left Front Door	HalfDollar	1-5	1		2
Right Rear Door	HalfDollar	1-5	1		4
Left Rear Door	HalfDollar	1-5			4
Right Quarter	-	No Dents			
Left Quarter	HalfDollar	6-15			7
Trunk	-	No Dents			



Colibri Scan Report

Horizontal

	Dime	Nickel	Quarter	HalfDollar	Oversize	D-Oversize
Trunk						
Hood	5	7	11	20	6	
Roof	3	13	22	55	26	1


Left

	Dime	Nickel	Quarter	HalfDollar	Oversize	D-Oversize
Left Rail		3	3	2	3	
Left Fender		2		2		
Left Front Door				1	1	
Left Rear Door		2		2		
Left Quarter	1	2		4		

Right

	Dime	Nickel	Quarter	HalfDollar	Oversize	D-Oversize
Right Rail		1		2		
Right Fender			1		1	
Right Front Door		2	2	6	1	
Right Rear Door			1	2	1	
Right Quarter						


Colibri Scan Report




Left Fender Left



Right Fender Right




Left Front Door Left



Right Front Door Right


Colibri Scan Report




Left Rear Door Left



Right Rear Door Right




Left Quarter Left




Right Quarter Right

Colibri Scan Report



Roof

Colibri Scan Report




Left Rail Left



Right Rail Right

Colibri Scan Report



Hood

No Image

Trunk Top

No Image

Trunk Bottom